\_ Note! No cross tee X1 X1 X1 MAINRUNNER X2 X2 X2 X2 X1 X1 X2 X1 X1 X2 X2 X2 X2 MAINRUNNER X 1 X2 X 1 X2 X2 X2 X 1 X2 X1 X2 X2 X1 X1 X2 X1 X2 MAINRUNNER MAINRUNNER All screws and other fastenings shown are indicative Specific fasteners should be chosen dependent on

Information:	

and illustrative only.

X-edge Change direction Two panel dimensions

substrates and materials being used.

Drawing Type: 31.03.2014 Drawing No.: Drawn by: Scale: 23.6.1.Corridors 1:2 Contact Information:

Rockfon

We kindly draw your attention to the fact that the above drawings should be considered as guidelines and therefore are without responsibility on the part of Rockfon.